

#SAFERCARSFORINDIA

Maruti Suzuki WAGONR












SPECIFICATIONS

Tested model	Maruti Suzuki WagonR
Body type	5 door hatchback - sedan
Year of publication	2023
Crash test weight (KG)	1013
VIN from which Rating applies	
Made in	India
Test valid for	India market

SAFETY EQUIPMENT

DRIVER	PASSENGER	REAR		
YES - STANDARD	YES - STANDARD	NOT APPLICABLE		
YES - STANDARD	YES - STANDARD	NOT AVAILABLE		
YES - STANDARD	YES - STANDARD	NOT AVAILABLE		
NOT AVAILABLE	NOT AVAILABLE	NOT APPLICABLE		
NOT AVAILABLE	NOT AVAILABLE	NOT AVAILABLE		
NOT AVAILABLE	NOT AVAILABLE	NOT AVAILABLE		
NOT AVAILABLE	NOT AVAILABLE	NOT AVAILABLE		
NOT AVAILABLE	NOT AVAILABLE	NOT AVAILABLE		
NOT APPLICABLE	NOT AVAILABLE	NOT AVAILABLE		
NOT APPLICABLE	NOT AVAILABLE	NOT AVAILABLE		
NOT APPLICABLE	NOT AVAILABLE	NOT APPLICABLE		
YES - STANDARD	YES - STANDARD	NOT AVAILABLE		
NOT AVAILABLE				
NOT AVAILABLE	NOT AVAILABLE			
NOT AVAILABLE				
NOT AVAILABLE NOT AVAILABLE				
	YES - STANDARD YES - STANDARD NOT AVAILABLE NOT AVAILABLE NOT AVAILABLE NOT AVAILABLE NOT APPLICABLE	YES - STANDARD YES - STANDARD YES - STANDARD YES - STANDARD NOT AVAILABLE NOT APPLICABLE NOT AVAILABLE		

ADULT OCCUPANT PROTECTION



Comments

Frontal impact: the protection offered to the driver's head was adequate and passenger's head was good. Driver's and passenger's neck showed good protection. Driver's chest showed weak protection and passenger's chest showed adequate protection. Driver's and passenger's knees showed marginal protection as they can impact with dangerous structures behind the fascia. Driver's tibias showed adequate and weak protection and passenger's tibias showed good protection. Footwell area was rated as unstable. The bodyshell was rated as unstable and not capable of withstanding further loadings.

Side impact: head, abdomen and pelvis protection was good while chest protection was marginal.

Side pole impact: not performed as the car does not offer side airbags.

SBR: the car offers SBR for both front occupants.

FSC: not available.

CHILD OCCUPANT PROTECTION

CHILD RESTRAINT SYSTEM

Dynamic score CRS Installation Score 0.00 (max 24.00) 3.40 (max 12.00)

Vehicle assessment score

0.00 (max 13.00)

	Child restraint	Dynamic score	CRS Type	Adjust	Position
18 month old child	Britax Roemer Baby Safe	Front 0.00 (8 max) Side 0.00 (4 max)	0+	Belted	RWF
3 year old child	Britax Roemer Duo Plus	Front 0.00 (8 max) Side 0.00 (4 max)	I	Belted	FWF

	Front Passenger	2nd row outboard	2nd row centre
ISOFIX	NOT AVAILABLE	NOT AVAILABLE	NOT AVAILABLE
i-Size	NOT AVAILABLE	NOT AVAILABLE	NOT AVAILABLE
Integrated CRS	NOT AVAILABLE	NOT AVAILABLE	NOT AVAILABLE

CRS INSTALLATION ASSESSMENT

	D 4 O O	E A 11
•	PASS	FAIL

FAIL • EXEMPT

		1ST ROW	2ND ROW		
REFERENCE LIST		LEFT	LEFT	CENTER	RIGHT
Group 0+	Peg Perego Viaggio Switchable (BELTED)	0	•	•	•
Group 0+	Roemer Baby Safe (ISOFIX / LEG)	N/A	N/A	N/A	N/A
Group 0+	Bébé Confort Stry Fix / Maxi Cosi Citi (BELTED	0	•	•	•
Group I	Peg Perego Viaggio Switchable FWF (BELTED)	0	•	•	•
Group I	Graco Cadeira Nautilus FWF (BELTED)	•	•	•	•
Group II/II	Cybex Solution M-Fix (BELTED)	0	•	•	•
Group II/II	Graco Cadeira Nautilus (BELTED)	0	•	•	•
MANUFACTURTER					
Q1.5	Britax Roemer Baby Safe (BELTED)	0	•	•	•
Q3	Britax Roemer Duo Plus (BELTED)	0	•	•	•

Comments

Frontal impact: the child seat for the 3 year old was installed FWF using the adult seatbelt and was not able to prevent excessive forward movement during the impact exposing the head to high risk of injuries. The 18 month old CRS was installed using the adult seatbelt RWF showing high risk for the head and weak protection to the chest. Vehicle based assessment scored zero points as the car does not offer 3 point belts in all seating positions. The manufacturer declined to recommend CRSs which explains the zero points in dynamic score. The vehicle does not offer standard ISOFIX and top tether anchorages. The Passenger airbag cannot be disconected in the case of a CRS intalled in the front passenger position.